Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	39250	((force load stress strain) near3 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5)).clm.	USPAT; EPO; JPO	OR	ON	2004/12/21 08:34
L2	46	1 near5 notch\$5.clm.	USPAT; EPO; JPO	OR	ON	2004/12/21 08:44
L3	19	2 and strain near3 gauge.clm.	USPAT; EPO; JPO	OR	ON	2004/12/21 08:45
L4	289	1 near5 (groove slide slit notch\$5).clm.	USPAT; EPO; JPO	OR	ON	2004/12/21 08:45
L5	46	4 and strain near3 gauge.clm.	USPAT; EPO; JPO	OR	ON	2004/12/21 08:46